

# Fire Extinguisher & Emergency Lighting Inspection Report

*For*

Your Facility  
1 Toronto Street  
Woodbridge, Ontario

*This Inspection was performed in accordance with applicable standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.*

*Inspection Date*  
*Jan 31, 2011*

Building: Your Facility  
Contact: Ronald Macdonald  
Title: Building Manager

Company: Steadfast Safety Services  
Contact: Arora Mukesh  
Title: Extinguisher Technician

# Executive Summary

Generated by: *BuildingReports.com*

Building Information								
<b>Building:</b> Your Facility					<b>Contact:</b> Ronald Macdonald			
<b>Address:</b> 1 Toronto Street					<b>Phone:</b> 416-746-7238			
<b>Address:</b>					<b>Fax:</b>			
<b>City/Province/Postal Code:</b> Woodbridge, Ontario					<b>Mobile:</b>			
<b>Country:</b> Canada					<b>Email:</b>			
Inspection Performed By								
<b>Company:</b> Steadfast Safety Services					<b>Inspector:</b> Arora Mukesh			
<b>Address:</b> 13 - 595 Middlefield Road					<b>Phone:</b> 416-332-0030			
<b>Address:</b>					<b>Fax:</b>			
<b>City/Province/Postal Code:</b> Toronto, ON M1V 3S2					<b>Mobile:</b>			
<b>Country:</b> Canada					<b>Email:</b> admin@steadfastsafety.com			
Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Fire	52	70.27%	52	100.00%	36	69.23%	16	30.77%
Lighting	22	29.73%	22	100.00%	20	90.91%	2	9.09%
<b>Totals</b>	<b>74</b>	<b>100%</b>	<b>74</b>	<b>100.00%</b>	<b>56</b>	<b>75.68%</b>	<b>18</b>	<b>24.32%</b>
Certification								
<b>Building:</b> Your Facility				<b>Company:</b> Steadfast Safety Services				
<b>Contact:</b> Ronald Macdonald				<b>Inspector:</b> Arora Mukesh				
<b>Signed:</b>				<b>Signed:</b>				

# Discrepancy Report

Generated by: [BuildingReports.com](http://BuildingReports.com)

Building: Your Facility				
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided, and where appropriate, code references are listed for your convenience. Devices/items that are listed on the Consumer Product Safety Commission website for recall are provided below.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
ScanID	Location	Problem	Reference	
<i>Fire</i>				
<b>Fire Extinguisher, A.B.C., 5 Lbs</b>				
13910098	Ground South production area ...	Missing Parts	NFPA 10 6.2.2 (6)	
14847210	Ground East Warehouse men's washroom			
14847211	Ground East Warehouse Loading dock 12	Handle Damaged	NFPA 10 6.2.2 (6)	
14847215	Ground Southeast Men's washroom Warehouse	Defective	NFPA 10 1.5.2	
14847217	Ground Southwest loading dock 1-2	Hydro Due		
14847222	Ground Northwest Maitenance	Passed		
<b>Fire Extinguisher, B.C., 2.5 Lbs</b>				
14847204	Ground FORKLIFT TOYOTA SNO.72516	Incorrect Size	NFPA 10 5.2.1	
<b>Fire Hose, Single Jacket, 75 ft</b>				
15093588	Ground Northwest POST- 4DA9			
15093589	Ground Northwest POST- opposite NW EXIT			
15093590	Ground Southwest between shipping office/wrapping machine			
13910099	Ground Inside Warehouse	Failed Test	NFPA 1962 7.2.2	
15093591	Ground South-center wrapping machine			
15093592	Ground East Warehouse men's washroom			
15093593	Ground East Warehouse packing storage area			
15093594	Ground Northeast Production area machine no.11			
15093596	Ground Northeast Production area machine no.18			
<i>Lighting</i>				
<b>Emergency Light, Dual Head Remote</b>				
13910100	Ground Inside warehouse	not accessible		
14847193	Ground North close to maintenance room in production area	Obstructed	NFPA 101	

# Proposed Solutions Report

Generated by: *BuildingReports.com*

Building: Your Facility				
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>				
🔍 ScanID	📍 Location	🔧 Solution	Cost	Fix
<b><i>Fire</i></b>				
<b>Fire Extinguisher, A.B.C., 5 Lbs</b>				
13910098	Ground South production area ...	Replace 2 missing 5 lb. ABC	T/M	<input type="checkbox"/>
14847210	Ground East Warehouse men's washroom		T/M	<input type="checkbox"/>
14847211	Ground East Warehouse Loading dock 12	Handle repair & recharge	T/M	<input type="checkbox"/>
14847215	Ground Southeast Men's washroom Warehouse	Recharge & Pressure gauge	T/M	<input type="checkbox"/>
14847217	Ground Southwest loading dock 1-2	Perform Hydro test	T/M	<input type="checkbox"/>
14847222	Ground Northwest Maintenance	Install proper wall bracket	T/M	<input type="checkbox"/>
<b>Fire Extinguisher, B.C., 2.5 Lbs</b>				
14847204	Ground FORKLIFT TOYOTA SNO.72516	Install 3A40BC VB Ext.	T/M	<input type="checkbox"/>
<b>Fire Hose, Single Jacket, 75 ft</b>				
15093588	Ground Northwest POST- 4DA9		T/M	<input type="checkbox"/>
15093589	Ground Northwest POST- opposite NW EXIT		T/M	<input type="checkbox"/>
15093590	Ground Southwest between shipping office/wrapping machine		T/M	<input type="checkbox"/>
13910099	Ground Inside Warehouse	10 Fire Hoses for H test	T/M	<input type="checkbox"/>
15093591	Ground South-center wrapping machine		T/M	<input type="checkbox"/>
15093592	Ground East Warehouse men's washroom		T/M	<input type="checkbox"/>
15093593	Ground East Warehouse packing storage area		T/M	<input type="checkbox"/>
15093594	Ground Northeast Production area machine no.11		T/M	<input type="checkbox"/>
15093596	Ground Northeast Production area machine no.18		T/M	<input type="checkbox"/>
<b><i>Lighting</i></b>				
<b>Emergency Light, Dual Head Remote</b>				
13910100	Ground Inside warehouse	Need access, 3 hours to test	T/M	<input type="checkbox"/>
14847193	Ground North close to maintenance room in production area	Gain access and test	T/M	<input type="checkbox"/>

# Notes & Recommendations

Generated by: BuildingReports.com

## Building: Your Facility

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

Note	Device Type	Location	Comment	ScanID
<b><i>Fire</i></b>				
1	Fire Extinguisher	Mezzanine East Exit production	Passed	14847203
	extinguisher mounted			
2	Fire Extinguisher	Ground East Warehouse men's washroom		14847210
	recharge the extinguisger 5lb ABC			
3	Fire Extinguisher	Ground East Warehouse Loading dock 12	Handle Damaged	14847211
	5lb flag,handle repair & recharge			
4	Fire Extinguisher	Ground Southeast Men's washroom Warehouse	Defective	14847215
	needs H-TEST 5lb ABC(20)			
5	Fire Extinguisher	Ground Southwest loading dock 1-2	Hydro Due	14847217
	needs H-TEST 5lb ABC (17)			
6	Fire Extinguisher	Ground Northwest Maitenance	Passed	14847222
	improper bracket			
7	Fire Extinguisher	Ground Forklift Nissan – F2(SILGAN 83162)	Passed	15093580
	New Fire Extinguisher – Forklift Jan-31			
8	Fire Extinguisher	Ground Forklift HYSTER40- rent	Passed	15093582
	fire extinguisher recharged- Jan-31 rental			
9	Fire Extinguisher	Ground Forklift Orange 25- rent	Passed	15093583
	fire extinguisher has been tagged			
10	Fire Extinguisher	Ground Forklift Toyota – N2	Passed	15093584
	New fire extinguisher forklift- Jan 31			
11	Fire Extinguisher	Ground Forklift Toyota – N1	Passed	15093585
	New fire extinguisher forklift- Jan 31			
12	Fire Extinguisher	Ground Forklift Nissan – N15	Passed	15093586

Note	Device Type	Location	Comment	ScanID
	new fire extinguisher forklift- Jan 31			
13	Fire Extinguisher	Ground North Production area machine 20	Passed	15093597
	This is new 5lb fire extinguisher			
14	Fire Extinguisher	Ground North Production area machine 17	Passed	15093598
	this is a new fire ext 5lb			
15	Fire Extinguisher	Ground South production area ...	Missing Parts	13910098
	...2 extinguishers missing			
16	Fire Extinguisher	Ground FORKLIFT TOYOTA SNO.C010H1976S HYSTER (4)	Passed	14847185
	Returned fireextinguisher after service Jan-31			
17	Fire Hose	Ground Inside Warehouse	Failed Test	13910099
	10 hoses for h test			
18	Fire Hose	Ground South-center wrapping machine		15093591
	going for H-Test			
19	Fire Hose	Ground East Warehouse men's washroom		15093592
	going for H-TEST Jan 31			
20	Fire Hose	Ground East Warehouse packing storage area		15093593
	going for H-Test			
21	Fire Hose	Ground Northeast Production area machine no.11		15093594
	going for H-test			
22	Fire Hose	Ground Northeast Production area machine no.18		15093596
	going for H-test			
23	Fire Hose	Ground Northwest POST- 4DA9		15093588
	gone for H-Test Jan-31			
24	Fire Hose	Ground Northwest POST- opposite NW EXIT		15093589
	noproper access to the hose			
25	Fire Hose	Ground Southwest between shipping office/wrapping machine		15093590
	going for H-Test Jan 31			

Note	Device Type	Location	Comment	ScanID
<b><i>Lighting</i></b>				
26	Emergency Light	Ground Inside warehouse	not accessible	13910100
			3 exit combo and 10 lrg units not accessible	
27	Emergency Light	Ground Northeast Electrical Exit north	Passed	14845474
			new battery 6-4.5=1	
28	Emergency Light	Ground Northeast Electrical Exit south	Passed	14845475
			battery changed 6-4.5=1	
29	Emergency Light	Ground Southwest storage spot no.4B14-4B15 in warehouse	Passed	14847190
			the test switch is missing{smashed}	
30	Emergency Light	Ground North close to maintenance room in production area	Obstructed	14847193
			no proper and safe access to the unit.	
31	Emergency Light	Ground Northeast Main Exit	Passed	14847198
			put in new 6-7=1 battery	
32	Emergency Light	Ground Northeast maintenance office dock 11-12	Passed	14847199
			put in 12-7=2 new battery	

# Inspection & Testing

Generated by: [BuildingReports.com](http://BuildingReports.com)

## Building: Your Facility

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred. For more information about an item, click on the link provided.*

Device Type	Location	ScanID : S/N	Service	Date Time
<b><i>Passed</i></b>				
<b>Fire</b>				
Fire Extinguisher, 5 Lbs, A.B.C.	Mezzanine East Exit production	14847203	Checked	01/31/11 2:45:55 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground FORKLIFT TOYOTA SNO.C010H1976S HYSTER (4)	14847185	Inspect	01/31/11 12:00:54 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Forklift HYSTER40-rent	15093582	Checked	01/31/11 12:07:45 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Forklift Nissan - F14(SILGAN 83160)	15093581	Checked	01/31/11 11:55:34 AM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Forklift Nissan - F2(SILGAN 83162)	15093580	Checked	01/31/11 11:49:35 AM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Forklift Nissan - N15	15093586	Checked	01/31/11 12:41:21 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Forklift Orange 25-rent	15093583	Checked	01/31/11 12:13:52 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Forklift Toyota - N1	15093585	Checked	01/31/11 12:24:35 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Forklift Toyota - N2	15093584	Checked	01/31/11 12:16:50 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Warehouse forklift with propane tank maintenance	14847223	Checked	11/29/10 3:06:18 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground East Warehouse mazznine	14847209	Checked	11/29/10 2:00:06 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground North Production area machine 17	15093598	Checked	01/31/11 3:07:46 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground North Production area machine 20	15093597	Checked	01/31/11 3:00:20 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground North Production area machine 3	14847206	Checked	11/29/10 2:27:20 PM
Fire Extinguisher, 5 Lbs, Carbon Dioxide	Ground North central, LAB	14847224	Checked	11/29/10 12:28:15 PM
Fire Extinguisher, 5 Lbs	Ground North central, production office side wall	14847226	Checked	11/29/10 12:21:51 PM
Fire Extinguisher, 5 Lbs	Ground North central, production office spare fire extinguisher	14847225	Checked	11/29/10 12:23:56 PM
Fire Extinguisher, 20 Lbs, A.B.C.	Ground Northeast electrical room south door	14845473	Checked	12/02/10 3:31:15 PM
Fire Extinguisher, 5 Lbs,	Ground Northeast Exit	14847205	Checked	11/29/10 2:32:00 PM



Device Type	Location	ScanID : S/N	Service	Date Time
A.B.C. Fire Extinguisher, 5 Lbs, A.B.C.	machine 7 Ground Northeast production area on post next to machine 12	14847202	Checked	11/29/10 2:48:23 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Northeast Sprinkler room	14847184	Checked	12/02/10 3:37:50 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Northwest Lunch room	14847221	Checked	11/29/10 12:48:47 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Northwest Warehouse	14847219	Checked	11/29/10 1:08:31 PM
Fire Extinguisher, 5 Lbs	Ground Northwest exit Warehouse side wall	14847220	Checked	11/29/10 1:04:02 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground South central warehouse adjacent to fire hose	14847207	Checked	11/29/10 2:09:50 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Southcentral Warehouse Exit	14847213	Checked	11/29/10 1:36:53 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Southeast Carrier Chiller 5	14847208	Checked	11/29/10 2:04:53 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Southeast Warehouse Exit	14847212	Checked	11/29/10 1:42:16 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Southwest loading dock 5-4	14847216	Checked	11/29/10 1:20:57 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Southwest Shipping Exit	14847214	Checked	11/29/10 1:31:21 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground West Warehouse EXIT	14847218	Checked	11/29/10 1:12:19 PM
Fire Extinguisher, 5 Lbs, A.B.C.	OFFICE 1ST FLOOR Above Main Entrance	14847234	Checked	11/29/10 10:55:20 AM
Fire Extinguisher, 5 Lbs, A.B.C.	OFFICE CENTRE 1ST FLOOR Above Main Entrance	14847229	Checked	11/29/10 11:43:24 AM
Fire Extinguisher, 5 Lbs, A.B.C.	OFFICE EXIT WEST 1ST FLOOR Above Main Entrance	14847230	Checked	11/29/10 11:40:02 AM
Fire Extinguisher, 5 Lbs, A.B.C.	OFFICE SUPPLY AREA 1ST FLOOR Above Main Entrance	14847228	Checked	11/29/10 11:46:17 AM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground Northeast Production area machine no.16	15093595	Checked	01/31/11 1:46:43 PM
<b>Lighting</b>				
Emergency Light, Dual Head Remote	1st floor Office above North Main Entrance-supply area	14847232	Checked	11/29/10 11:16:07 AM
Emergency Light, Combination	1st floor Office above Northwest Main Exit	14847233	passed	11/29/10 11:34:56 AM
Emergency Light, Dual Head Remote	Ground Center warehouse/production partition wall	14847189	Checked	12/01/10 1:01:17 PM
Emergency Light, Dual Head Remote	Ground North above the time machine	14847195	Checked	11/30/10 2:52:34 PM
Emergency Light, Dual Head Remote	Ground North close to women washroom in production area	14847194	Checked	11/30/10 2:59:36 PM
Emergency Light, Combination	Ground North Machine no.3 Exit	14847196	Checked	11/30/10 2:44:52 PM
Emergency Light,	Ground North Main Entrance	14847235	Checked	11/29/10 10:38:03 AM

Device Type	Location	ScanID : S/N	Service	Date Time
Combination Emergency Light, Dual Head Remote	Ground North central, production office back wall	14847227	Checked	11/29/10 12:09:40 PM
Emergency Light, Combination	Ground Northeast Electrical Exit north	14845474	Inspect	01/31/11 2:41:42 PM
Emergency Light, Combination	Ground Northeast Electrical Exit south	14845475	Inspect	01/31/11 2:43:31 PM
Emergency Light, Combination	Ground Northeast Machine no.8 Exit	14847197	Checked	11/30/10 2:38:34 PM
Emergency Light, Combination	Ground Northeast Main Exit	14847198	Inspect	01/31/11 2:23:46 PM
Emergency Light, Dual Head Remote	Ground Northeast maintenance office dock 11-12	14847199	Inspect	01/31/11 2:54:11 PM
Emergency Light, Combination	Ground Northwest Warehouse Exit	14847201	Checked	11/29/10 3:15:17 PM
Emergency Light, Dual Head Remote	Ground South warehouse post 5B	14847188	Checked	12/01/10 1:18:39 PM
Emergency Light, Dual Head Remote	Ground South warehouse post 6B	14847187	Checked	12/01/10 1:23:42 PM
Emergency Light, Dual Head Remote	Ground Southwest close to shipping dock 3-4	14847191	Checked	11/30/10 3:38:45 PM
Emergency Light, Dual Head Remote	Ground Southwest close to shipping dock 9	14847192	Checked	11/30/10 3:27:47 PM
Emergency Light, Dual Head Remote	Ground Southwest Shipping and receiving office	14847200	Checked	11/29/10 3:23:43 PM
Emergency Light, Dual Head Remote	Ground Southwest storage spot no.4B14-4B15 in warehouse	14847190	Inspect	12/01/10 12:46:54 PM
<b><i>Failed/Other</i></b>				
<b>Fire</b>				
Fire Extinguisher, 2.5 Lbs, B.C.	Ground FORKLIFT TOYOTA SNO.72516	14847204	Inspect	12/01/10 1:33:00 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground East Warehouse Loading dock 12	14847211	Inspect	01/31/11 1:25:00 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground East Warehouse men's washroom	14847210		01/31/11 1:31:53 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Northwest Maitenance	14847222	Inspect	11/29/10 12:42:11 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground South production area ...	13910098	Inspect	12/02/10 5:00:30 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Southeast Men's washroom Warehouse	14847215	Inspect	01/31/11 1:07:13 PM
Fire Extinguisher, 5 Lbs, A.B.C.	Ground Southwest loading dock 1-2	14847217	Inspect	01/31/11 1:09:10 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground East Warehouse men's washroom	15093592		01/31/11 1:36:23 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground East Warehouse packing storage area	15093593		01/31/11 1:39:38 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground Inside Warehouse	13910099	Inspect	12/02/10 4:57:13 PM

Device Type	Location	ScanID : S/N	Service	Date Time
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground Northeast Production area machine no.11	15093594		01/31/11 1:44:35 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground Northeast Production area machine no.18	15093596		01/31/11 1:50:35 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground Northwest POST-4DA9	15093588		01/31/11 12:57:25 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground Northwest POST-opposite NW EXIT	15093589		01/31/11 1:02:19 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground South-center wrapping machine	15093591		01/31/11 1:21:44 PM
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Ground Southwest between shipping office/wrapping machine	15093590		01/31/11 1:16:05 PM
<b>Lighting</b>				
Emergency Light, Dual Head Remote	Ground Inside warehouse	13910100	Inspect	12/02/10 4:55:06 PM
Emergency Light, Dual Head Remote	Ground North close to maintenance room in production area	14847193	Inspect	11/30/10 3:15:19 PM

# Service Summary

Generated by: BuildingReports.com

Building: Your Facility		
<i>The Service Summary section provides an overview of the services performed in this report.</i>		
Device Type	Service	Quantity
<b><i>Failed/Other</i></b>		
Emergency Light, Dual Head Remote	Inspect	2
Fire Extinguisher, 2.5 Lbs, B.C.	Inspect	1
Fire Extinguisher, 5 Lbs, A.B.C.		1
Fire Extinguisher, 5 Lbs, A.B.C.	Inspect	5
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.		8
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Inspect	1
<b>Total</b>		<b>18</b>
<b><i>Passed</i></b>		
Emergency Light, Combination	Checked	4
Emergency Light, Combination	Inspect	3
Emergency Light, Combination	passed	1
Emergency Light, Dual Head Remote	Checked	10
Emergency Light, Dual Head Remote	Inspect	2
Fire Extinguisher, 20 Lbs, A.B.C.	Checked	1
Fire Extinguisher, 5 Lbs, A.B.C.	Checked	29
Fire Extinguisher, 5 Lbs, A.B.C.	Inspect	1
Fire Extinguisher, 5 Lbs, Carbon Dioxide	Checked	1
Fire Extinguisher, 5 Lbs	Checked	3
Fire Hose, 75 ft, Single Jacket, 1 1/2 Dia.	Checked	1
<b>Total</b>		<b>56</b>

# Fire Extinguisher Maintenance Report

Generated by: *BuildingReports.com*

Building: Your Facility					
<p><i>This report provides details on the Hydrostatic Test and Maintenance/Breakdown dates for fire extinguishers. Items that will need either of these services at any time in the next two years are displayed. Items are grouped together by year for budgeting purposes.</i></p>					
ScanID	Location	Serial #	Hydro	Serviced	Mfr Date
<b>Due in 2009</b>					
<b>Breakdown/Maintenance</b>					
<b>Fire Extinguisher, B.C., 2.5 Lbs</b>					
14847204	Ground FORKLIFT TOYOTA SNO.72516		11/01/03	11/01/03	11/08/03
<b>Due in 2011</b>					
<b>Breakdown/Maintenance</b>					
<b>Fire Extinguisher, A.B.C., 5 Lbs</b>					
14847218	Ground West Warehouse EXIT		11/01/17	11/01/11	11/01/05
14847206	Ground North Production area machine 3		11/01/17	11/01/11	11/01/05
14847205	Ground Northeast Exit machine 7		11/01/19	11/01/11	11/01/93
14847202	Ground Northeast production area on post next to machine 12		11/01/17	11/01/11	11/01/05
<b>Due in 2012</b>					
<b>Hydrostatic Test</b>					
14847222	Ground Northwest Maitenance		11/01/12	11/01/18	11/01/00
14847214	Ground Southwest Shipping Exit		11/01/12	11/01/18	11/01/00
<b>Due in 2013</b>					
<b>Breakdown/Maintenance</b>					
<b>Fire Extinguisher, A.B.C., 5 Lbs</b>					
14847216	Ground Southwest loading dock 5-4		11/01/19	11/01/13	11/01/96
14847212	Ground Southeast Warehouse Exit		11/01/19	11/01/13	11/01/96
14847209	Ground East Warehouse mazznine		11/01/19	11/01/13	11/01/07
14847211	Ground East Warehouse Loading dock 12		11/01/19	11/01/13	11/01/07
<b>Hydrostatic Test</b>					
<b>Fire Extinguisher, A.B.C., 20 Lbs</b>					
14845473	Ground Northeast electrical room south door		11/01/13	11/01/19	11/01/90
<b>Fire Extinguisher, A.B.C., 5 Lbs</b>					
14847234	OFFICE 1ST FLOOR Above Main Entrance		11/01/13	11/01/19	11/29/10
14847230	OFFICE EXIT WEST 1ST FLOOR Above Main Entrance		11/01/13	11/01/19	11/29/10
14847229	OFFICE CENTRE 1ST FLOOR Above Main Entrance		11/01/13	11/01/19	11/29/10
14847228	OFFICE SUPPLY AREA 1ST FLOOR		11/01/13	11/01/19	11/29/10

ScanID	Location	Serial #	Hydro	Serviced	Mfr Date
	Above Main Entrance				
14847221	Ground Northwest Lunch room		11/01/13	11/01/19	11/01/01
14847219	Ground Northwest Warehouse		11/01/13	11/01/19	11/01/01
14847213	Ground Southcentral Warehouse Exit		11/01/13	11/01/19	11/01/01
14847208	Ground Southeast Carrier Chiller 5		11/01/13	11/01/20	11/01/01
14847207	Ground South central warehouse adjacent to fire hose		11/01/13	11/01/20	11/01/01
14847184	Ground Northeast Sprinkler room		11/01/13	11/01/19	11/01/01
13910098	Ground South production area ...		11/01/13	11/01/19	11/01/90
<b>Fire Extinguisher, Carbon Dioxide, 5 Lbs</b>					
14847224	Ground North central, LAB		11/01/13		11/29/10

# Fire Hose Maintenance Report

Generated by: *BuildingReports.com*

Building: Your Facility					
<i>This report provides details on the Hydrostatic Test dates for fire hose. Items that will need this service at any time in the next two years are displayed. Items are grouped together by year for budgeting purposes.</i>					
ScanID	Location	Serial #	Hydro	Serviced	Mfr Date
<b><i>Due in 2011</i></b>					
<b>Hydrostatic Test</b>					
<b>Fire Hose, Single Jacket, 75 ft</b>					
15093588	Ground Northwest POST- 4DA9		11/01/11	11/01/17	11/01/11
15093589	Ground Northwest POST- opposite NW EXIT		11/01/11	11/01/17	11/01/11
15093590	Ground Southwest between shipping office/wrapping machine		11/08/11	11/01/16	11/01/96
15093591	Ground South-center wrapping machine		11/01/11	11/01/17	11/01/11
15093592	Ground East Warehouse men's washroom		11/01/11	11/01/14	11/01/96
15093593	Ground East Warehouse packing storage area		11/01/11	11/01/14	11/01/96
15093594	Ground Northeast Production area machine no.11		11/01/11	11/01/14	11/01/96
15093595	Ground Northeast Production area machine no.16		11/01/11	11/01/14	11/01/96
15093596	Ground Northeast Production area machine no.18		11/01/11	11/01/14	11/01/96
<b><i>Due in 2013</i></b>					
<b>Hydrostatic Test</b>					
13910099	Ground Inside Warehouse		11/01/13	11/01/19	11/01/01

# Exit/Emergency Lighting

Generated by: BuildingReports.com

Building: Your Facility									
<i>Exit and Emergency Lighting items are listed with each of the relevant measurements for pre and post test voltages, the load current, charge rate, and the rated voltage and current capacity of standby batteries. The remote heads indicate the number of other items that get their supply voltage from this item. Items are listed by type, and grouped by Passed or Failed/Other.</i>									
Location	Model #	Post Chk	Rated Volts	Pre-Test Volts	Post-Test Volts	Load Amps	Charge Amps	Remote Heads	Amp Hours
<b>Passed</b>									
<b>Emergency Light, Combination</b>									
1st floor Office above Northwest Main Exit	ES6-36-LR	<input type="checkbox"/>		6.99	6.14	20Watt	2.7	...nil	
Ground North Main Entrance	ES6-36-LR	<input type="checkbox"/>		6.93	6.10	20Watt	2.7	...nil	
Ground Northwest Warehouse Exit	ES6-50-LRU	<input type="checkbox"/>		6.93	6.10	20Watt	2.7	...nil	
Ground Northeast Machine no.8 Exit	ES6-36-LR	<input type="checkbox"/>		6.99	6.14	20Watt	2.7	...nil	
Ground North Machine no.3 Exit	ES6-36-LR	<input type="checkbox"/>		6.94	6.15	20Watt	2.7	...nil	
Ground Northeast Main Exit	ES6-36-LR	<input type="checkbox"/>	6	6.99	6.14	20Watt	2.7	...nil	7
Ground Northeast Electrical Exit north	ES6-36-LR	<input type="checkbox"/>	6	6.99	6.14	20Watt	2.7	...nil	4.5
Ground Northeast Electrical Exit south	ES6-36-LR	<input type="checkbox"/>	6	6.99	6.14	20Watt	2.7	...nil	4.5
<b>Emergency Light, Dual Head Remote</b>									
1st floor Office above North Main Entrance-supply area	B12-250	<input type="checkbox"/>		13.66	11.97	20Watt	7.7	.11	
Ground North central, production office back wall	6-36	<input type="checkbox"/>		7.2	6.36	18 Watt	3.1	...nil	
Ground Southwest Shipping and receiving office	B12-250	<input type="checkbox"/>		13.86	12.13	two head	9.2	ma	
Ground North above the time machine	B12-250	<input type="checkbox"/>		13.66	11.97		7.7	nil	
Ground North close to women washroom in production area	B12-250	<input type="checkbox"/>		13.59	11.99		7.7	nil	
Ground Southwest close to shipping dock 9	B12-250	<input type="checkbox"/>		12.83	11.92		7.6ma	nil	
Ground Southwest close to shipping dock 3-4	B12-250	<input type="checkbox"/>		12.80	12.15		7.8ma	nil	
Ground Southwest storage spot no.4B14-4B15 in warehouse	B12-250	<input type="checkbox"/>		..13.17	..12.35		8.2	nil	
Ground Center warehouse/production partition wall	B12-250	<input type="checkbox"/>		..13.19	..12.43		7.8	nil	
Ground South warehouse post 5B	B12-250	<input type="checkbox"/>		..13.19	..12.43		7.8	nil	



			Rated	Pre-Test	Post-Test	Load	Charge	Remote	Amp
Ground South warehouse post 6B	B12-250	<input type="checkbox"/>		..13.1 9	..12.4 3		7.8	nil	
Ground Northeast maintenance office dock 11-12	B12-200	<input type="checkbox"/>	12	13.86	12.13	two head	9.2 ma		7
<b><i>Failed/Other</i></b>									
<b>Emergency Light, Dual Head Remote</b>									
Ground North close to maintenance room in production area	B12-250	<input type="checkbox"/>			.			nil	
Ground Inside warehouse	B12-250	<input type="checkbox"/>		..13.1 9	..12.4 3		7.8	nil	

# Inventory & Warranty Report

Generated by: *BuildingReports.com*

Building: Your Facility				
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Item	Category	% of Inventory	Quantity	
Emergency Light	Lighting	29.73%	22	
Fire Extinguisher	Fire	56.76%	42	
Fire Hose	Fire	13.51%	10	
Type	Qty	Model #	Description	Manufacture Date
<b><i>New (under 90 days)</i></b>				
<b>Buckeye</b>				
Fire Extinguisher	5	5 HI SA40 ABC	A.B.C.	11/01/2011
<b>Strike First</b>				
Fire Extinguisher	2	WBDL-ABC310L V	A.B.C.	11/01/2011
Fire Hose	3		Single Jacket	11/01/2011
<b><i>In Service - 90 Days - 1 Year</i></b>				
<b>Beghelli</b>				
Emergency Light	2	ES6-36-LR	Combination	12/02/2010
Emergency Light	5	B12-250	Dual Head Remote	12/01/2010
Emergency Light	3	ES6-36-LR	Combination	11/30/2010
Emergency Light	5	B12-250	Dual Head Remote	11/30/2010
Emergency Light	2	ES6-36-LR	Combination	11/29/2010
Emergency Light	1	ES6-50-LRU	Combination	11/29/2010
Emergency Light	1	B12-200	Dual Head Remote	11/29/2010
Emergency Light	2	B12-250	Dual Head Remote	11/29/2010
<b>Lumacell</b>				
Emergency Light	1	6-36	Dual Head Remote	11/29/2010
<b>Strike First</b>				
Fire Extinguisher	2	WBDL-ABC 310P		11/29/2010
Fire Extinguisher	4	WBDL-ABC 310P	A.B.C.	11/29/2010
<b>Buffalo</b>				
Fire Extinguisher	1	BSCO	Carbon Dioxide	11/29/2010
<b><i>In Service - 1 Year to 2 Years</i></b>				
<b>Strike First</b>				
Fire Extinguisher	1	WBDL-ABC340L V	A.B.C.	11/01/2009

Type	Qty	Model #	Description	Manufacture Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>Buckeye</b>				
Fire Extinguisher	1	5HI SA40 ABC	A.B.C.	11/01/2008
<b>no name</b>				
Fire Extinguisher	1	no information	A.B.C.	11/01/2008
<b>Strike First</b>				
Fire Extinguisher	1	WBDL-ABC 340LV	A.B.C.	11/01/2008
Fire Extinguisher	1	WBDL-ABC340L V	A.B.C.	11/01/2008
<b><i>In Service - 3 Years to 5 Years</i></b>				
<b>Flag Fire</b>				
Fire Extinguisher	2	ABC-050-J.	A.B.C.	11/01/2007
<b><i>In Service - 5 Years to 10 Years</i></b>				
<b>Flag Fire</b>				
Fire Extinguisher	3	ABC-050-J.	A.B.C.	11/01/2005
<b>no name</b>				
Fire Extinguisher	1	no information	B.C.	11/08/2003
<b>Strike First</b>				
Fire Extinguisher	1	WBDL-ABC 310P		11/01/2001
Fire Extinguisher	1	WBDL- ABC 310P	A.B.C.	11/01/2001
Fire Extinguisher	1	WBDL-ABC 310P	A.B.C.	11/01/2001
Fire Extinguisher	4	WBDL-ABC 5	A.B.C.	11/01/2001
Fire Hose	1		Single Jacket	11/01/2001
<b><i>In Service - 10 Years to 15 Years</i></b>				
<b>Strike First</b>				
Fire Extinguisher	1	WBDL-ABC 310P	A.B.C.	11/01/2000
Fire Extinguisher	1	WBDL-ABC 5	A.B.C.	11/01/2000
Fire Extinguisher	1	WBDL-ABC 5	A.B.C.	11/01/1998
<b>Steel Fire</b>				
Fire Extinguisher	1	WBSF-ABC5A	A.B.C.	11/01/1996
<b>Strike First</b>				
Fire Extinguisher	3	WBDL-ABC 5	A.B.C.	11/01/1996
Fire Hose	6		Single Jacket	11/01/1996
<b><i>In Service - 15 Years to 25 Years</i></b>				

Type	Qty	Model #	Description	Manufacture Date
<b>Strike First</b>				
Fire Extinguisher	1	WBDL-ABC 5	A.B.C.	11/01/1993
<b>Diamond</b>				
Fire Extinguisher	1	WBDL ABC....5	A.B.C.	11/01/1990
Fire Extinguisher	1	WBDL ABC 20	A.B.C.	11/01/1990